A Review of Trespassing Accident and Suicide on Railway Track for Pedestrian Safety

Eng. Abeysiri Munasinghe Asoka 148301 B

Dissertation submitted in partial fulfilment of the requirements for the degree Master of Highway and Traffic Engineering

Department of Civil Engineering
University of Moratuwa
Sri Lanka

June 2018

DECLARATION OF THE CANDIDATE AND THE SUPERVISOR

I declare that this is my own work and this dissertation does not incorporate without

acknowledgement any material previously submitted for a Degree or Diploma in any other

University or institute of higher learning and to the best of my knowledge and belief it does

not contain any material previously published or written by another person except where the

acknowledgement is made in the text.

Also, I hereby grant to University of Moratuwa the non-exclusive right to reproduce and

distribute my dissertation, in whole or in part in print, electronic or other medium. I retain the

right to use this content in whole or part in future works (such as articles or books).

Signature:

Date:

The above candidate has carried out research for the Masters dissertation under my

supervision.

Signature of the supervisor:

Date:

i

ABSTRACT

Railway accident prevention and protection are a key part of a wider picture of transport safety.

The rail sector thus needs to improve its knowledge of trespassing and suicide related accidents

in order to work out suitable responses by analysing measures already taken.

More than 100 people die each year in Sri Lanka due to the collision with a train due to suicides

or trespassing. This research analyses the data related to above accidents recorded in Sri Lanka

Railways. The following factors were considered for the analysis.

1. Distance from Colombo

2. Day and Month of the incident

3. The gender and age of the victim

4. Geometry of the railway track

5. Noise level of the surrounding area of the incident

6. Visibility between trespassers and train drivers

7. Weather condition

8. Permissible speed in the incident area

9. Availability of short paths avoiding railway track

The review of articles and data gives a picture of where, how and who is involved in suicide

and trespass accidents.

Here the accidents implying persons out of level crossings, or "accidents to persons", mostly

involve unauthorized persons crossing or walking along the tracks, usually because of

convenience. Another, much more common cause of fatalities and significant accidents out of

level crossings is the suicidal intent of persons entering the railway premises to voluntarily be

hit by a train.

The main similarities between railway suicides and trespassing accidents relate to gender and

location: the victims in railway suicides and trespassing accidents and observed trespassers

were predominantly male, and most of the railway suicides and trespassing accidents occurred

in densely populated areas.

Keywords: Railway; safety; suicide; trespassing

ii

ACKNOWLEDGEMENTS

It is with great pleasure and satisfaction I present this research report for the partial fulfilment of requirements of the Degree of Master of Engineering in Highway and Traffic Engineering in Faculty of Engineering, University of Moratuwa.

First I wish to thank the Transport Engineering Division of Department of Civil Engineering, Faculty of Engineering, University of Moratuwa for selecting me to follow this Master's course in Highway and Traffic Engineering.

I thank Sri Lanka Railways, my employer, for the sponsorship I received to follow this course as well as for releasing me to study for this degree on part time basis.

Next I wish to thank Prof. J.M.S.J. Bandara for his correct guidance and continuous support throughout this research. The knowledge I gathered from him apart this research work but in the lecture room was also valuable and greatly helped me.

I wish to thank all the staff of Transport Engineering Division of Department of Civil Engineering, Faculty of Engineering, University of Moratuwa, including visiting lecturers for their continuous efforts in enhancing our knowledge in this particular subject of highway engineering. My special thanks go to Prof. W.K Mampearachchi, Dr. H.R. Pasindu, Dr. Dimantha De Silva and Mr. Loshaka Perera.

I do thank Eng. B.A.P. Ariyaratna, General Manager of Railways, Eng. J. Uthayakumar, Additional General Manager (Infrastructure), Eng. S.G. Premkumar, Chief Engineer (Way and Works), who greatly helped me in understanding the concepts of highway engineering in my work place.

Next I wish to thank my colleagues in the lecture room and the work place for their valuable assistance in following this course.

I extend my thanks to my dear father late Mr. A.M.K. Sumanadasa and my dear mother Mrs. A.L.A. Punyalatha who are the divine strength and courage behind all the successes in my life.

Finally I wish to thank to my wife Mrs. Indrani Manike and my three children for their patience and love for me throughout the period of this course

TABLE OF CONTENTS

D	ECLAF	RATION OF THE CANDIDATE AND THE SUPERVISOR	i
A	BSTRA	ACT	ii
A	.CKNO	OWLEDGEMENTS	iii
T	ABLE	OF CONTENTS	iv
L	IST OF	F FIGURES	vi
L	IST OF	F TABLES	vii
1	INT	TRODUCTION	1
	1.1	General Background	1
	1.2	Objectives	1
	1.3	Problem Statement	2
	1.4	Scope of the Report	2
2	LIT	TERATURE REVIEW	3
	2.1	Different intensions of trespassers	3
	2.2	Rules and Regulations to prevent trespassing	4
3	ANA	ALYSIS	8
	3.1	Methodology	8
	3.2	Analysis	10
	3.2.	.1 Total Number of Cases in each year	10
	3.2.2	2 Month	12
	3.2.3	3 Day	13
	3.2.4	4 Gender of the victim	14
	3.2.5	.5 Age of the victim	15
	3.2.0	.6 Visibility	16
	3.2.	.7 Noise level of surrounding area	17
	3.2.8	.8 Speed of the train	18
	3.2.9	9 Availability of parallel lines	19
	3.2	10 Weather Conditions	20

	3.2.	11 Train Line	21
	3.2.	12 Type of train	22
4	COl	NCLUSION & RECOMMENDATIONS	23
	4.1	Conclusion & Recommendations	23
5	Bibl	liography	24
6	APF	PENDICES	25
	6.1	Table of Data	25
	6.2	Photos of field visits	<u>34</u>

LIST OF FIGURES

Figure 1: Extract from the main record book of Railway	5
Figure 2: Extract from the part I of working time table issued by the	Railway Operating
Department	7
Figure 3: Distance from Colombo	9
Figure 4: Cases per million train km	10
Figure 5 : Analysis of cases 2011-2016	11
Figure 6 : Cases in monthly basis	12
Figure 7: Cases according to day	13
Figure 8 : Gender of the Victim	14
Figure 9 : Age of the victim	15
Figure 10 : Visibility	16
Figure 11: Noise Level of surrounding area	17
Figure 12 : Speed of the train	18
Figure 13 : Availability of parallel Roads	19
Figure 14: Weather Conditions	20
Figure 15 : Train Line	21
Figure 16: Type of train	22

LIST OF TABLES

Table 1: Distance from Colombo	8
Table 2: Total Number of Cases in each year	10
Table 3 : Cases in Monthly Basis	12
Table 4 : Cases according to day	13
Table 5 : Gender of the victim	14
Table 6 : Age of the victim	15
Table 7 : Visibility	16
Table 8 : Noise Level of surrounding area	17
Table 9 : Speed of the train	18
Table 10 : Availability of parallel Roads	19
Table 11 : Weather Conditions	20
Table 12 : Train Line	21
Table 13 : Average type of train per day	22